CERTIFICATE OF COMPLIANCE

Certificate Number 20170811 – E93776

Report Reference E93776 – 20081214

Issue Date 2017-AUGUST-11

Issued to: EUCHNER GMBH + CO KG

Kohlhammerstrasse 16

Leinfelden

70771 Echterdingen, GERMANY

This is to certify that Auxiliary Devices representative samples of (See Addendum)

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 508, "Industrial Control Equipment"

CSA-C22.2 No. 14, "Industrial Control Equipment,"

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/



CERTIFICATE OF COMPLIANCE

Certificate Number 20170811 – E93776

Report Reference E93776 – 20081214

Issue Date 2017-AUGUST-11

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Addendum -

Safety switches: NQ02VZ-5000, NQ03VZ-5000, NQ11VZ-5000, NQ12VZ-5000.

Enclosed auxiliary Device, locking switch: TQ1-0302G024-5000, TQ1-1202SG024-5000, TQ1-1211G024-5000, TQ1-1211SG024-5000, TQ2-0302G024-5000, TQ2-1202SG024-5000, TQ2-1211SG024-5000.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, pleas contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

(U)